

RECEIVED CENTRAL FAX CENTER

OCT 2 0 2006

North America Intellectual Property Corporation

P.O. BOX 506, Merrifield, VA 22116, U.S.A.

Voice Mail: 302-729-1562

FAX: 806-498-6673

c-mail:winstonhsu@naipo.com

Customer No.: 27765

Fax To: DANG, KHANH

Tel.: (571) 272-3626

Art Unit: 2111

Fax: (571) 273-8300

From: Winston Hsu, Registration No. 41,526

Serial No.: 10/605,195 Patent No.: 7,073,008

Attorney Docket No.:MTKP0074USA

Subject: Citation of Prior Art under 37 CFR §1.501.

Total Pages: 39 pages (including cover page)

Winston Hsu 10/20/2006

MTKP0074USA0 D2 I

013.34963.8

说 明 书 第3/5页

搭配至一容错式数据传输接口装置中,可在主控的接口电路发生故障状况时,立即以其来取代原有的主控的PCI-SCSI接口电路的数据传输接口功能,使得数据传输不会因主控的接口电路发生故障状况而中断。

附图说明

本发明的实质技术内容及其实施例已用图解方式详细绘制于本说明书的附图之中。此些附图的内容简述如下:

ref があたらべつ エヘロ・シャ がは かは から はった (43) / cc. ー はい / cc. しょ (**) , はよ ーキ・ロマット (25)

Best Available Copy